
Note: You must be sure that the link pin is engaged PROPERLY with the hammer, if the link pin IS NOT PROPERLY REPLACED, you may damage the hammer/cylinder assembly.



Remember......Operator error is not covered by warranty!!